

# Informations de sécurité sur l'utilisation des substances extrêmement préoccupantes (SVHC)

## INFORMATIONS SUR L'ARTICLE 33 DU RÈGLEMENT REACH CONCERNANT LES SUBSTANCES EXTRÊMEMENT PRÉOCCUPANTES

Cher client,

L'article 33, paragraphe 1, du règlement REACH (CE 1907/2006) vise à permettre aux clients des produits fournis de prendre toute mesure de gestion des risques susceptibles de résulter de la présence dans les articles de substances extrêmement préoccupantes (SVHC) énumérées sur la liste actuelle des substances candidates à l'autorisation, afin de garantir leur utilisation sécurisée.

FORD soutient les objectifs sous-jacents du règlement REACH en général et de l'article 33 (paragraphe 1) en particulier, qui sont en accord avec notre propre engagement à promouvoir la fabrication, la manipulation et l'utilisation responsables de nos produits.

### **Identification des substances extrêmement préoccupantes (SVHC)**

À notre connaissance, sur la base des informations reçues de notre chaîne d'approvisionnement et de nos propres données de produits, les substances extrêmement préoccupantes (SVHC) présentes dans les articles contenant une quantité supérieure à 0,1% de la masse, sont celles figurant sur la « Liste des SVHC » correspondante pour le véhicule/la pièce spécifique.

### **Informations de sécurité spécifiques sur l'utilisation des produits contenant des SVHC**

Le cas échéant, des informations spécifiques sur l'utilisation sécurisée des articles contenant des SVHC sont ajoutées à la « Liste des SVHC » correspondante pour le véhicule/la pièce en question.

### **Informations de sécurité générales sur l'utilisation des produits contenant des SVHC**

Chaque véhicule FORD est livré avec un manuel du propriétaire, qui comprend des informations sur l'utilisation sécurisée pour les propriétaires/exploitants du véhicule. Les informations FORD sur la réparation et l'entretien des véhicules et des pièces d'origine incluent également des informations sur l'utilisation sécurisée pour le personnel de service.

Lorsqu'elles sont présentes dans des pièces de ce véhicule, les SVHC figurant sur la « Liste des SVHC » correspondante pour le véhicule/la pièce concerné(e) sont intégrées de manière à minimiser l'exposition potentielle des clients, et à exclure le danger pour l'homme ou l'environnement tant que le véhicule et ses pièces sont utilisés comme prévu et que les réparations et l'entretien sont effectués

conformément aux instructions techniques relatives à ces activités et aux bonnes pratiques habituelles de l'industrie.

Un véhicule en fin de vie ne peut être éliminé légalement dans l'Union européenne que dans un centre agréé de destruction (ATF). Les pièces du véhicule doivent être éliminées conformément à la réglementation locale en vigueur et aux directives des autorités locales.

## Modèle : FORD MUSTANG

### Liste des substances extrêmement préoccupantes (SVHC) candidates à l'Agence européenne des produits chimiques (ECHA) au 1<sup>er</sup> juillet 2017

#### Informations de sécurité spécifiques sur l'utilisation des produits contenant des SVHC

Aucune information de sécurité spécifique n'est requise. Suivez les informations de sécurité générales sur l'utilisation des produits.

Commodity	REACH SVHCs
<b>A/C Compressor</b>	1-Methyl-2-pyrrolidone [872-50-4]
	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
	N,N-Dimethylformamide [68-12-2]
<b>ABS/ESC Module</b>	Imidazolidine-2-thione [96-45-7]
<b>Accessories</b>	C,C'-azodi(formamide) [123-77-3]
	Diboron-trioxide [1303-86-2]
<b>Air Brakes</b>	Imidazolidine-2-thione [96-45-7]
<b>AIS - Air Cleaner and Low Pressure Ducts</b>	Lead(II,IV)-oxide [1314-41-6]
	Lead-monoxide [1317-36-8]
<b>Alternator</b>	4,4'-Isopropylidenediphenol [80-05-7]
	Acrylamide [79-06-1]
	Diboron-trioxide [1303-86-2]
<b>Antenna</b>	Diboron-trioxide [1303-86-2]
<b>Audio and Navigation Head Units</b>	Diboron-trioxide [1303-86-2]
	Imidazolidine-2-thione [96-45-7]
	Lead titanium zirconium oxide [12626-81-2]
	Lead-monoxide [1317-36-8]
	Silicic acid, lead salt [11120-22-2]
<b>Body Structure - Floor Pan - Front Floor and Side Sill</b>	Boric acid [10043-35-3]
<b>Body Structure - Hood Assembly (incl Hinge/Supt)</b>	C,C'-azodi(formamide) [123-77-3]
<b>Bodyside, Wheel Arch, Rocker Moldings</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]

<b>Brake - Parking</b>	Boric acid [10043-35-3]
	C,C'-azodi(formamide) [123-77-3]
	Diboron-trioxide [1303-86-2]
<b>Brakes - Caliper &amp; Anchor Brkt Assy (Front, Rear)</b>	Cobalt sulphate [10124-43-3]
<b>CHMSL</b>	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
<b>EDS Wiring Assembly &amp; Components</b>	1,2-Benzenedicarboxylic acid, di-C6-8-branched alkyl esters, C7-rich [71888-89-6]
	1,2-Benzenedicarboxylic acid, di-C7-11-branched and linear alkyl esters [68515-42-4]
	1-Methyl-2-pyrrolidone [872-50-4]
	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	4,4'-Isopropylidenediphenol [80-05-7]
	Diboron-trioxide [1303-86-2]
	Nonoxinol [9016-45-9]
<b>Electronic Control Panel and CCH</b>	Diboron-trioxide [1303-86-2]
	Lead titanium zirconium oxide [12626-81-2]
	Lead-monoxide [1317-36-8]
<b>Electronic Modules - Amplifiers</b>	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene [13560-89-9]
	Diboron-trioxide [1303-86-2]
	Lead titanium zirconium oxide [12626-81-2]
	Lead-monoxide [1317-36-8]
<b>Electronic Modules - Headlamp</b>	Diboron-trioxide [1303-86-2]
<b>Electronic Modules - SYNC</b>	4,4'-Isopropylidenediphenol [80-05-7]
	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
	Lead-titanium-trioxide [12060-00-3]
<b>Engine Covers and Badges</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
<b>Evaporator and Blower Assembly (HVAC Module)</b>	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
<b>Exhaust Cold End (Muffler &amp; Output Pipe Assembly)</b>	Sodium borate, decahydrate [1303-96-4]
<b>Exhaust Hot End (Catalytic Converter)</b>	Refractory ceramic fibres [142844-00-6]
<b>Floor Mat</b>	1-Methyl-2-pyrrolidone [872-50-4]
	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
	Silicic acid, lead salt [11120-22-2]
<b>Fuel Injection</b>	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
<b>Fuel Lines</b>	Diboron-trioxide [1303-86-2]
<b>Headlamp / Side Marker</b>	1-Methyl-2-pyrrolidone [872-50-4]
	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
	Silicic acid, lead salt [11120-22-2]
<b>Instrument Cluster</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	Boric acid [10043-35-3]
	Diboron-trioxide [1303-86-2]
	Lead titanium zirconium oxide [12626-81-2]
	Lead-monoxide [1317-36-8]

	Silicic acid, lead salt [11120-22-2]
<b>Interior Lighting</b>	Diboron-trioxide [1303-86-2]
<b>Mirrors</b>	4,4'-Isopropylidenediphenol [80-05-7]
	Diboron-trioxide [1303-86-2]
	Silicic acid, lead salt [11120-22-2]
<b>Other</b>	1-Methyl-2-pyrrolidone [872-50-4]
	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
	4,4'-Isopropylidenediphenol [80-05-7]
	C,C'-azodi(formamide) [123-77-3]
	Diboron-trioxide [1303-86-2]
	Imidazolidine-2-thione [96-45-7]
	Lead-monoxide [1317-36-8]
	Nonoxinol [9016-45-9]
	Phenol, dimethyl-, phosphate (3:1) [25155-23-1]
	Poly(oxy-1,2-ethanediyl), alpha-(4-nonylphenyl)-omega-hydroxy-,branc... [127087-87-0]
<b>Park Assist</b>	Lead-monoxide [1317-36-8]
<b>PCV System</b>	Lead-monoxide [1317-36-8]
<b>PEM</b>	Diboron-trioxide [1303-86-2]
<b>Plastic Bumpers and Fascias</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol [25973-55-1]
<b>PT Sensors</b>	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
<b>Rain and Daylight Sensor</b>	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
<b>Receiver Assembly/CD (Radio)</b>	4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride [19438-60-9]
<b>Sealing - Door Dynamic Seals</b>	C,C'-azodi(formamide) [123-77-3]
	Imidazolidine-2-thione [96-45-7]
<b>Shifter Cables/Brackets - Auto</b>	Cobalt sulphate [10124-43-3]
	N,N-Dimethylacetamide [127-19-5]
<b>Side and Rear Vision (BLIS)</b>	Lead-titanium-trioxide [12060-00-3]
<b>Speakers / Tweeters</b>	N,N-Dimethylacetamide [127-19-5]
<b>Steering Wheel, Drive Air Bag</b>	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
<b>Switches - General Use</b>	Diboron-trioxide [1303-86-2]
<b>Switches - Headlamp. Window &amp; Door</b>	Diboron-trioxide [1303-86-2]
<b>Taillamp / Redundant</b>	Diboron-trioxide [1303-86-2]
	Lead-monoxide [1317-36-8]
<b>TPMS</b>	1,2-Dimethoxyethane [110-71-4]
	1,3-Propanesultone [1120-71-4]
<b>Transmission - Auto</b>	Diboron-trioxide [1303-86-2]
<b>Transmission - Manual</b>	Diboron-trioxide [1303-86-2]
<b>Transmission (Auto) - Lines/Tubes (Oil Cooler)</b>	C,C'-azodi(formamide) [123-77-3]
<b>Wheel</b>	1,3,5-Tris(oxiranylmethyl)-1,3,5-triazine-2,4,6(1H,3H,5H)-trione [2451-62-9]
<b>Wiper Assembly (Rear, Front) &amp; Washer System</b>	Diboron-trioxide [1303-86-2]
	Hexahydromethylphthalic-anhydride [25550-51-0]